




Tools Required -(2) 9/16" Sockets/Wrenches -Tape Measure -Torque Wrench

- Place guide-in mounts on cradle beam as shown and fasten with 3/8" x 2 1/4" stainless steel bolts and aluminum nuts. Torque to 35 ft-lb.
- 2. Install PVC guide-in tubes on guide-in mounts as shown.



## **CONTENTS OF:** P-1200, P-1600 & PWC-1300 SINGLE VERTICAL PVC GUIDE-IN KIT P/N 511-02940-00 (2) PVC GUIDE-IN TUBES WITH CAPS - P/N 511-02942-00 0 0 0 0 (2) GUIDE-IN MOUNTS - P/N 111-00270-00 **FASTENERS FOR:** P-1200, P-1600 & PWC-1300 SINGLE VERTICAL GUIDE-IN

P/N 001-70112-00

(4) 3/8" x 2 1/4" BOLTS

TORQUE TO 35 ft. lbs.

(1) FASTENER KIT - P/N 511-04235-00

P/N 001-76349-00

(4) 3/8" NUTS

1/12/04 511-02940-00

007-11823-00