
# FLOE HORIZONTAL BUMPER ADD ON KIT INSTALLATION INSTRUCTIONS

KIT P/N 510-03003-00






© FLOE International, Inc. 48473 State Hwy. 65 McGregor, MN 55760 All rights reserved

# Horizontal Bumper Exploded View P/N 510-03003-00

<u>NO.</u>	<u>Part no.</u>	<u>QTY.</u>	<u>DESCRIPTION</u>
1	002-02203-01	. 2	Plate, Dock Accessory
2	001-70107-00	. 2	HHCS, 3/8-16 x 1 1/4" 18-8 ss
3	001-76071-00	. 2	Nut, Nylock 3/8"-16 Alum.



# REMOVE BACKER ON TAPE rain hole 8" bolts

## Step 1


Slide the end cap without the drain hole off the bumper and slide (2) 3/8" bolts into the track on the bumper.

### Step 2

Remove the backing from the tape and slide the cap back on. Pull the sides of the cap out while sliding the cap over the tape.

Step 3

Attach the bumper to the two brackets provided using the (2) bolts and nuts as shown. With the location of the drain hole on the cap to be the bottom side.



CAP WITH NO DRAIN HOLE